



Plate XXV.—Plan of workings in State of Maine Mine, showing areas of stopping. Small dots indicate stopes in footwall fissure, large dots stopes in hanging wall fissures.