

EARTH FISSURES AND RELATED SUBSIDENCE FEATURES ADJACENT TO THE TUCSON AQUEDUCT, CENTRAL ARIZONA PROJECT, PINAL AND PIMA COUNTIES, ARIZONA

Steven Slaff
1993

EXPLANATION

- Boundary of area covered by aerial photography
- Area not field-checked because it was included in earlier investigations (Slaff and others, 1989; Slaff, 1991)
- Feature that may be an earth fissure or subsidence-related
- Area of one or more earth fissures reported previously (Caito and Sogge, 1982; Raymond and Bartell, 1985)

ARIZONA GEOLOGICAL SURVEY
Open-File Report 93-11
Plate 5 of 6