Arizona Geological Survey Contributed Map CM-94-G

TRACE OF MAIN DISPLACEMENT SURFACE (BEDROCK / BASIN-FILL CONTACT) OF PIRATE FAULT ZONE, WEST FLANK OF SANTA CATALINA MOUNTAINS, PIMA AND PINAL COUNTIES, AZ

William R. Dickinson

Dept Geosciences, Univ Arizona

1994

Fault Contact (Heavy Line)
Dashed Where Approximate,
Dotted Where Concealed
(beneath terrace or pediment gravel)



ARIZONA GEOLOGICAL SURVEY
CONTRIBUTED MAP CM-94-G
sheet 1 of 1, with text