

EARTH FISSURES AND RELATED SUBSIDENCE FEATURES ADJACENT TO THE TUCSON AQUEDUCT, CENTRAL ARIZONA PROJECT, PINAL AND PIMA COUNTIES, ARIZONA

Steven Slaff
1993

EXPLANATION

Boundary of area covered by aerial photography

Area not field-checked because it was included in earlier investigations (Slaff and others, 1989; Slaff, 1991)

Feature that may be an earth fissure or subsidence-related

Area of one or more earth fissures reported previously (Caito and Sogge, 1982; Raymond and Bartell, 1985)

ARIZONA GEOLOGICAL SURVEY
Open-File Report 93-11
Plate 2 of 6